

From: [Moore, Gary](#)
To: [Sean Gavlas](#)
Subject: Pictures of FJ Doyle Bldg
Date: Friday, September 28, 2018 2:15:07 PM
Attachments: [ATT00001.txt](#)

Sean

A portion of the building looks painted (tan). The roof metal is painted (tan) and the white metal is painted from factory. The tan paint was done in the 1990's according to Garry Doyle. The interior roof looks like it has soot on it.

We need to sample the interior roof for sure. I would add the interior roof as 2 separate samples. You may be able to get soot samples but it may need to be wipe.

Please right this up and send the plan to me.

Also, please note the interior lighting that will have to be addressed.

Electrical to building needs to be disconnected.

The key to the door will be placed on the north side of building on the west side of green trash can under a concrete core. I have key to lock on the interior of the building for east garage door.

You need to bring a tall ladder to the inspection and sampling. I have a ladder but you need to let me know if I need to bring it.

Thanks
Gary Moore

Sent from my iPad